Qty:

: WINDOW

: D33001

: N/A

NIA:

: 4/5/2006

: D3300 REV A

User

Wednesday, 3/29/2006 3:56:25 PM

Linda Lacelle

Process Sheet

Drawing Name

Part Number

Material

Due Date

Description:

Drawing Number

Project Number

Drawing Revision

Each

4 Um:

Customer

: CU-DAR001 Dart Helicopters Services

Job Number

Estimate Number

: 26396 7 : 10695

P.O. Number

:NIA

This Issue Prsht Rev.

First Issue

Written By

Previous Run

: 3/29/2006

: NC

: NIA : 24347

Type

: SMALL /MED FAB

: NHASEC COMMENTBELOW : SHE ABOUR USER IT DATE

Checked & Approved By Comment

: Est A 04.11.30 New Issue KJ/RF

S.O. No. : N/A

Additional Product

Job Number:

Seq. #:

Machine Or Operation:

SHEAR

SHEAR 1.0



Comment: SHEAR

Cut window: 13.20" x 24.20"

2.0

MACRLICS125

1/8" Polycast II Sheet

662



Comment: Qtv

255 9375 sf(s)/Unit Total: 1023/7500 sf(s)

1/8" Polycast II Sheet

Material: Polycast II Clear Acrylic sheet per MIL-P-5425, 0.125" thick

(M-ACRYLIC-S.125) Batch: 17-626

SMALL FAB 1 3.0

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Trim as per template D3300-1T1 Deburr, break all sharp edges 0.010 to 0.015

Engrave part number and batch number as per Dwg D3300

4.0 QC5 INSPECT WORK TO CURRENT STEP



Comment: INSPECT WORK TO CURRENT STEP

SMALL FAB 1 5.0

SMALL & MEDIUM FAB RESOURCE 1



Comment: SMALL & MEDIUM FAB RESOURCE 1

Identify, wrap in foam and Stock



SB 06/03/0.

Dart Aerospace Ltd

W/O:			WORK ORDER	CHANGES				
DATE	STEP	PROC	EDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	!	PAR #:	Fault Category:	NCR: Y	es No DQ	A:		04/04
				Q	A: N/C Close	d:	_ Date: _	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)								
DATE		Description of NC		Verification						
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector		

NOTE: Date & initial all entries

Date: User:

Wednesday, 3/29/2006 3:56:25 PM

Linda Lacelle

Process Sheet

Customer: CU-DAR001 Dart Helicopters Services

Drawing Name: WINDOW

Job Number: 26396

Part Number: D33001

Job Number:



Seq. #:


Machine Or Operation:

Description:

6.0

PACKAGING 1

PACKAGING RESOURCE #1



Comment: PACKAGING RESOURCE #1

Identify and Stock

Location:_

DOCUMENT CONTROL



7.0



Comment: DOCUMENT CONTROL

Inspection Level 21



a 26.04.04

Job Completion



Dart Ae	rospace L	td							
W/O:			W	ORK ORDER CH	ANGES				
DATE	STEP	PRO	ROCEDURE CHANGE		Ву	Date 0	Approva Chief Eng Prod Mgr	Approval QC Inspector	
Part No	:	PAR #:	Fault Cate	egory:	NCF	R: Yes	No DQA:	Date:	
				· ·				Date:	
NCR:		1	WORK ORD	ER NON-CONFO	RMANCE	(NCR)		
DATE STEP Description of NC		Description of NC	Initial	Corrective Action		Sign &	Verificati	on Approva	Approval


NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCR)			
DATE		Description of NC		Corrective Action Section B	Varification			
	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector

NOTE: Date & initial all entries





	DESIGN	DRAWN BY	DART AEROSPACE LTI HAWKESBURY, ONTARIO, CANADA)
Ì	CHECKED	APPROVED	DRAWING NO. D3300 SHE	REV. A ET 1 OF 1
	DATE 04.10.08		WINDOW	SCALE 1:5
T	A	04.10.08	NEW ISSUE	



D3300-1 WINDOW

- 1) MATERIAL: POLYCAST II CLEAR ACRYLIC SHEET PER MIL-P-5425 0.125" THICK
- (REF DART SPEC. M-ACRYLIC-S.125)
 2) TOLERANCES ARE PER DART QSI 018 UNLESS OTHERWISE NOTED
 3) ALL DIMENSIONS ARE IN INCHES
- 4) TRIM USING D3300-1T1 TEMPLATE